




1941 Temporary Office / Converted to
Dam Tenders Residence / Office



1945 Mechanic Shop
Inefficient for a
O & M Shop

Rock fall Mitigation



Patch in Canal Wall Due to Rock Fall




Annually Rocks This
Size Roll Down the
Slope
200 - 400 lbs


Slope Stabilization







Concrete Box Flume



Need for Lining




Construction Joint Failure





Deterioration of Concrete Wall



Liner to slow concrete deterioration, stabilize canal footing and increase water efficiency

